

An underwater photograph showing a stream bed. The water is clear, revealing a dense layer of green, needle-like aquatic plants (likely sparganium) growing from the bottom. Interspersed among the plants are several brown, decaying leaves and thin, light-colored sticks or twigs. The overall scene depicts a natural, somewhat cluttered aquatic environment.


Samordnat recipientkontrollprogram
för Broviken och dess tillflöden

Uppströmsarbete

maria.elfstrom@norrvatten.se



Uppströmspåverkan






Många verksamheter och bäckar små... som mynnar i Natura 2000 Broviken

- Högbytorp – 700 000 ton avfall
- Galoppverksamhet
- Skällsta industriområde och Bro samhälle
- Golfbana
- Coops rikslager
- SL:s tågdepå
- Tillkommande kraftvärmeverk och biogasanläggning
- Många detaljplaner på gång



Upplands-Bro

KOMMUNEN SOM GER PLATS






Tillflödena





Provtagning i Broviken





Vad som provtas i vatten, sediment och biota

- Bekämpningsmedel
- PCB
- SFÄ och PRIO-ämnen
- Makrofyter (natura 2000)
- Vattenkemi
- Näringsämnen
- Kiselalger
- Växtplankton
- Bottenfauna



Hur togs programmet fram?

- Konsult tog fram förslag
- Utgick från vilka verksamheter som låg uppströms och som var på gång
- Via miljöavdelningen som har tillsyn
- Länsstyrelsens miljöskydd
- Startades andra halvåret 2015
- Uppmärksammades av Mälarens vattenvårdsförbund 😊